Date of Reinspection: 10/18/2023

School: Administration Building -3rd floor & common areas

Inspector Name: Lynne Brimhall

Address: Tufts Building 167 Holland Street, Somerville, MA

Inspector Signature: Vinn

License #: AI 061691

Material	Location (Homogeneous Area)	QTY	Friable	Phys Assess Category	Assumed ACM	Sample Date ACM Y or N	Recommendation	Amount/Location of Damage; Type of Damage	Schedule Begin/Complete	Special Cleaning
Gray HVAC mastic	301M, 314M	5 SF	NF	5	Υ		O & M			N
Foam insulation	309M, 314M, 306M, 301M	N/A	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Fiberglass insulation	309M, 318M	N/A	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Pink fiberglass batt insulation	309M	N/A	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Window glazing	310	450 LF	NF	5	Υ		O&M			N
Prefab windows	Throughout 3 rd floor	N/A	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Window glazing on prefab	167 Holland entrance	100 LF	NF	5	Y		O&M			N
Beige vinyl cove base	Entrance near 211, entrance	210 LF	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Associated silicone mastic	near 142, 167 Holland entrance, 314M, 306M, 318M		N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A

Туре	Amount	Friability
T-TSI	SF-Square feet	F-Friable
S-Surfacing	LF-Linear feet	NF-Non-friable
M - Miscellane	ous	

Assessment Categories for Friable Materials

- 1. Damaged or significantly damaged TSI
- 2. Damaged (D) surfacing
- 3: Significantly damaged (SD) surfacing
- 4: Damaged or significantly damaged misc.
- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)

Date of Reinspection: 10/18/2023

School: Administration Building -3rd floor & common areas

Inspector Name: Lynne Brimhall

Address: Tufts Building 167 Holland Street, Somerville, MA

Inspector Signature: Synne Brimhall

License #: AI 061691

Material	Location (Homogeneous Area)	QTY	Friable	Phys Assess Category	Assumed ACM	Sample Date ACM Y or N	Recommendation	Amount/Location of Damage; Type of Damage	Schedule Begin/Complete	Special Cleaning
Gray vinyl cove base	142, 310, storage closet	251 LF	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Associated silicone mastic			N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Black vinyl cove base	Foyer at 300	88 LF	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Associated silicone mastic			N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
2x2 Gray ceramic floor tile grout	319B	156 SF	NF	6	Y		O & M			N
2x2 Gray ceramic floor tile associated adhesive/ thin set			NF	6	Y		O & M			N
12" Slate floor	Foyer at 300	448 SF	NF	6	Υ		O & M			N
Blue rubber floor	167 Holland entrance, rear, stairs, elevator	300 SF	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A

Туре	Amount	Friability
T-TSI	SF-Square feet	F-Friable
S-Surfacing	LF-Linear feet	NF-Non-friable
M - Miscellane	ous	

Assessment Categories for Friable Materials

1. Damaged or significantly damaged TSI

2. Damaged (D) surfacing

3: Significantly damaged (SD) surfacing

4: Damaged or significantly damaged misc.

- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)

School: Administration Building -3rd floor & common areas

Address: Tufts Building 167 Holland Street, Somerville, MA

Date of Reinspection: 10/18/2023

Inspector Name: Lynne Brimhall

Inspector Signature:

License #: AI 061691

Material	Location (Homogeneous Area)	QTY	Friable	Phys Assess Category	Assumed ACM	Sample Date ACM Y or N	Recommendation	Amount/Location of Damage; Type of Damage	Schedule Begin/Complete	Special Cleaning
12 x 12 Beige w/gray floor tile	318M	48 SF	NF	6	Y		O & M			N
Associated mastic			NF	6	Υ		O & M			N
Poured gray floor	319A	156 SF	NF	6	Υ		O & M			N
Carpet (gray/ blue/ beige)	Throughout 3 rd floor unless noted Black carpet -	20,000 SF	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Black carpet	Reception	500 SF	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Carpet mastic	Throughout entire 3 rd floor	20,500 SF	NF	7	Υ		O & M			N
Wood floor	309M, 306M, 301M	600 SF	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
Brick	310, 308 windows,	5,903 SF	NF	5	Y		O & M			N
Associated mortar	Entrance near 211, Entrance near 142, Foyer at 300, 2 nd floor landing		NF	5	Y		O & M			N

Туре	Amount	Friability
T-TSI	SF-Square feet	F-Friable
S-Surfacing	LF-Linear feet	NF-Non-friable

M - Miscellaneous

Assessment Categories for Friable Materials

- 1. Damaged or significantly damaged TSI
- 2. Damaged (D) surfacing
- 3: Significantly damaged (SD) surfacing
- 4: Damaged or significantly damaged misc.
- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)
 - *Potential for future disturbance for categories 5, 6, & 7 Access, Vibration, Air Erosion: L-low M-medium H-high

Date of Reinspection: 10/18/2023

School: Administration Building -3rd floor & common areas

Inspector Name: Lynne Brimhall

Address: Tufts Building 167 Holland Street, Somerville, MA

Inspector Signature: Junne Brimhal

License #: AI 061691

Material	Location (Homogeneous Area)	QTY	Friable	Phys Assess Category	Assumed ACM	Sample Date ACM Y or N	Recommendation	Amount/Location of Damage; Type of Damage	Schedule Begin/Complete	Special Cleaning
CMU	314M	180 SF	NF	5	Υ		O & M			N
Associated mortar			NF	5	Υ		O & M			N
Wood wall	310 (wall with windows)	300 SF	N/A	N/A	N	N – per regulations	N/A	N/A	N/A	N/A
4x4 Ceramic wall tile grout	319A sink wall and associated toilets	240 SF	NF	5	Y		O & M			N
4x4 Ceramic wall tile adhesive/ thin set			NF	5	Y		O & M			N

Туре	Amount	Friability
T-TSI	SF-Square feet	F-Friable
S-Surfacing	LF-Linear feet	NF-Non-friable
M - Miscellane	ous	

Assessment Categories for Friable Materials

1. Damaged or significantly damaged TSI

le 2. Damaged (D) surfacing

3: Significantly damaged (SD) surfacing

4: Damaged or significantly damaged misc.

- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)

Date of Reinspection: 10/18/2023

School: Administration Building -3rd floor & common areas

Inspector Name: Lynne Brimhall

Address: Tufts Building 167 Holland Street, Somerville, MA

Inspector Signature: _/

License #: AI 061691

Material	Location (Homogeneous Area)	QTY	Friable	Phys Assess Category	Assumed ACM	Sample Date ACM Y or N	Recommendation	Amount/Location of Damage; Type of Damage	Schedule Begin/Complete	Special Cleaning
Sheetrock	322B, 322C	66,300	F	4	Υ		Sample to prove			N
	Conference,	SF					negative until such			
	Storage closet,						time as it is proven			
	322D, Area						negative include in			
	outside of						O&M Plan			
	conference									
	rooms, area									
	outside of 322E,									
	322E, 322H, Area									
	outside of 323A,									
	323A, 323B, Area									
	outside 323C,									
	Lower ceiling of									
	large room by									
	323A, closet by									
	323C, 315A walk									
	through to 311,									
	2 nd floor landing,									
	309M, 306M,									
	301M, 323C,									
	309M, reception									
	area & main area									
	of 318, Copier									
	room, 318D,									
	318E,318F,									
	318G,318H,									
	318I, Corridors in									

Туре	Amount	Friability					
T-TSI	SF-Square feet	F-Friable					
S-Surfacing	LF-Linear feet	NF-Non-friable					
M - Miscellaneous							

Assessment Categories for Friable Materials

- 1. Damaged or significantly damaged TSI
- 2. Damaged (D) surfacing
- 3: Significantly damaged (SD) surfacing
- 4: Damaged or significantly damaged misc.
- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)

School: Administration Building -3rd floor & common areas

Address: Tufts Building 167 Holland Street, Somerville, MA

Date of Reinspection: 10/18/2023

Inspector Name: Lynne Brimhall

Inspector Signature:

License #: AI 061691

318,318J, 318S,				
small corridor,				
318K, area				
outside of 318L,				
318L, 318M,				
318N, 318O,				
Hallway at				
finance				
reception,				
hallway outside				
finance hall by				
315, mechanical				
rooms by suite				
308, 317, 317B,				
317A,316, 316A,				
316B, 316C,				
316D, 315, 315A,				
315B, 316D, 315,				
315B, area				
outside 308 &				
309, 308, 309				
Entry, Office B				
area, 308C,				
308D, 308A,				
308B, 309A,				
corridor outside				
of 306M, 307,				
306, 302M,				
Ceiling of				
entrance near				

Friability Type Amount T-TSI SF-Square feet F-Friable S-Surfacing LF-Linear feet NF-Non-friable M - Miscellaneous

3: Significantly damaged (SD) surfacing

2. Damaged (D) surfacing

4: Damaged or significantly damaged misc.

1. Damaged or significantly damaged TSI

- **Assessment Categories for Friable Materials** 5: Suspect or proven ABCM with the potential for D (*one moderate)
 - 6: Suspect or proven ABCM with the potential for SD (*one high)
 - 7. Any remaining suspect or proven ACBM (*all low)

School: Administration Building -3rd floor & common areas

Address: Tufts Building 167 Holland Street, Somerville, MA

Date of Reinspection: 10/18/2023

Inspector Name: Lynne Brimhall

Inspector Signature: Junne Brimhall

License #: AI 061691

211, Entrance				
near 142, area				
outside 226,				
322B, halls at				
321, M314				
ceiling, Lower				
ceiling of large				
room by 323A,				
closet by 323C,				
315A walk				
through to 311,				
2 nd floor landing,				
318 main office,				
324, 301M				

Type	Amount	Friability
T-TSI	SF-Square feet	F-Friable
S-Surfacing	LF-Linear feet	NF-Non-friab
M - Miscellane	ous	

Assessment Categories for Friable Materials

1. Damaged or significantly damaged TSI

ole 2. Damaged (D) surfacing

3: Significantly damaged (SD) surfacing

4: Damaged or significantly damaged misc.

- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)

Date of Reinspection: 10/18/2023

School: Administration Building -3rd floor & common areas

Inspector Name: Lynne Brimhall

Address: Tufts Building 167 Holland Street, Somerville, MA

Inspector Signature: / / //

License #: AI 061691

Material	Location (Homogeneous Area)	QTY	Friable	Phys Assess Category	Assumed ACM	Sample Date ACM Y or N	Recommendation	Amount/Location of Damage; Type of Damage	Schedule Begin/Complete	Special Cleaning
Joint	322B, 322C	66,300	F	5	Υ		Sample to prove			N
compound	Conference,	SF					negative until such			
	Storage closet,						time as it is proven			
	322D, Area						negative include in			
	outside of						O&M Plan			
	conference									
	rooms, area									
	outside of 322E,									
	322E, 322H, Area									
	outside of 323A,									
	323A, 323B, Area									
	outside 323C,									
	Lower ceiling of									
	large room by									
	323A, closet by									
	323C, 315A walk									
	through to 311,									
	2 nd floor landing,									
	309M, 306M,									
	301M, 323C,									
	309M, reception									
	area & main area									
	of 318, Copier									
	room, 318D,									
	318E,318F,									
	318G,318H,									
	318I, Corridors in									

TypeAmountFriabilityT-TSISF-Square feetF-FriableS-SurfacingLF-Linear feetNF-Non-friableM - Miscellaneous

Assessment Categories for Friable Materials

- 1. Damaged or significantly damaged TSI
- 2. Damaged (D) surfacing
- 3: Significantly damaged (SD) surfacing
- 4: Damaged or significantly damaged misc.
- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)

School: Administration Building -3rd floor & common areas

Address: Tufts Building 167 Holland Street, Somerville, MA

Date of Reinspection: 10/18/2023

Inspector Name: Lynne Brimhall

Inspector Signature: Number Bri

License #: AI 061691

318,318J, 318S,				
small corridor,				
318K, area				
outside of 318L,				
318L, 318M,				
318N, 318O,				
Hallway at				
finance				
reception,				
hallway outside				
finance hall by				
315, mechanical				
rooms by suite				
308, 317, 317B,				
317A,316, 316A,				
316B, 316C,				
316D, 315, 315A,				
315B, 316D, 315,				
315B, area				
outside 308 &				
309, 308, 309				
Entry, Office B				
area, 308C,				
308D, 308A,				
308B, 309A,				
corridor outside				
of 306M, 307,				
306, 302M,				
Ceiling of				
entrance near				

TypeAmountFriabilityT-TSISF-Square feetF-FriableS-SurfacingLF-Linear feetNF-Non-friableM - Miscellaneous

Assessment Categories for Friable Materials

- 1. Damaged or significantly damaged TSI
- 2. Damaged (D) surfacing
- 3: Significantly damaged (SD) surfacing
- 4: Damaged or significantly damaged misc.
- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)

Date of Reinspection: 10/18/2023

School: Administration Building -3rd floor & common areas

Inspector Name: Lynne Brimhall

Address: Tufts Building 167 Holland Street, Somerville, MA

Inspector Signature: Junne Raimha

License #: AI 061691

211, Entrance				
near 142, area				
outside 226,				
322B, halls at				
321, M314				
ceiling, Lower				
ceiling of large				
room by 323A,				
closet by 323C,				
315A walk				
through to 311,				
2 nd floor landing,				
318 main office,				
324, 301M				

Туре	Amount	Friability
T-TSI	SF-Square feet	F-Friable
S-Surfacing	LF-Linear feet	NF-Non-friabl
M - Miscellane	ous	

Assessment Categories for Friable Materials

1. Damaged or significantly damaged TSI

ole 2. Damaged (D) surfacing

3: Significantly damaged (SD) surfacing

4: Damaged or significantly damaged misc.

- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)

Date

Date of Reinspection: 10/18/2023

School: Administration Building -3rd floor & common areas

Inspector Name: Lynne Brimhall

Address: Tufts Building 167 Holland Street, Somerville, MA

Inspector Signature:

License #: AI 061691

Material	Location (Homogeneous Area)	QTY	Friable	Phys Assess Category	Assumed ACM	Sample Date ACM Y or N	Recommendation	Amount/Location of Damage; Type of Damage	Schedule Begin/Complete	Special Cleaning
Very thick	Work room 321,	17,081	F	5	Υ		Sample to prove			N
fissured	hall by work	SF					negative until such			
ceiling tile	room, 2 nd						time as it is proven			
	common hall,						negative include in			
	office hall,						O&M Plan			
	storage, small									
	storage, 322A,									
la 3	322B, 322D,									
	large room by									
	322E, 322 H,									
	large room by									
	223A, 323A,									
	waiting area by									
	323C, 323C,									
	323D, reception,									
	copier in 318,									
	318C, 318D,									
	Kayla Health,									
	318E, 318N,									
	3180, back hall,									
	Hall by 318 at									
	furnace, 319B,									
	317 Suite (A -B),									
	316 Suite (A-C),									
	315, 315A, 315B,									
	309A, 309B, hall									
	to 308/309,									

Туре	Amount	Friability
T-TSI	SF-Square feet	F-Friable
S-Surfacing	LF-Linear feet	NF-Non-friable
M - Miscellane	ous	

Assessment Categories for Friable Materials

- 1. Damaged or significantly damaged TSI
- 2. Damaged (D) surfacing
- 3: Significantly damaged (SD) surfacing
- 4: Damaged or significantly damaged misc.
- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)
 - *Potential for future disturbance for categories 5, 6, & 7 Access, Vibration, Air Erosion: L-low M-medium H-high

School: Administration Building -3rd floor & common areas

Address: Tufts Building 167 Holland Street, Somerville, MA

Date of Reinspection: 10/18/2023

Inspector Name: Lynne Brimhall

License #: AI 061691

1	1						I	1
307, 301 kitchen,								
301B, 301C,								
301D, 301E,								
301F, 302, 304,								
305, 303A, 303D,								
303C, 310A								
open, 310A,								
310E, Hall at								
310E, 310B,								
310C, 311,								
Testing room,								
kitchen 310, hall								
Finance hall, hall								
310								
	301D, 301E, 301F, 302, 304, 305, 303A, 303D, 303C, 310A open, 310A, 310E, Hall at 310E, 310B, 310C, 311, Testing room, 311B, 311A, kitchen 310, hall at 310, hall by 322A, 322A, 322B, 322D, Suite 318, Finance hall, hall by stairwell, Finance by exit, Suite 303, Room	308C, 308D, rear hall 308, 306, 307, 301 kitchen, 301B, 301C, 301D, 301E, 301F, 302, 304, 305, 303A, 303D, 303C, 310A open, 310A, 310E, Hall at 310E, 310B, 310C, 311, Testing room, 311B, 311A, kitchen 310, hall at 310, hall by 322A, 322A, 322B, 322D, Suite 318, Finance hall, hall by stairwell, Finance by exit, Suite 303, Room	308C, 308D, rear hall 308, 306, 307, 301 kitchen, 301B, 301C, 301D, 301E, 301F, 302, 304, 305, 303A, 303D, 303C, 310A open, 310A, 310E, Hall at 310E, 310B, 310C, 311, Testing room, 311B, 311A, kitchen 310, hall at 310, hall by 322A, 322A, 322B, 322D, Suite 318, Finance hall, hall by stairwell, Finance by exit, Suite 303, Room	308C, 308D, rear hall 308, 306, 307, 301 kitchen, 301B, 301C, 301D, 301E, 301F, 302, 304, 305, 303A, 303D, 303C, 310A open, 310A, 310E, Hall at 310E, 310B, 310C, 311, Testing room, 311B, 311A, kitchen 310, hall at 310, hall by 322A, 322A, 322B, 322D, Suite 318, Finance hall, hall by stairwell, Finance by exit, Suite 303, Room	308C, 308D, rear hall 308, 306, 307, 301 kitchen, 301B, 301C, 301D, 301E, 301F, 302, 304, 305, 303A, 303D, 303C, 310A open, 310A, 310E, Hall at 310E, 310B, 310C, 311, Testing room, 311B, 311A, kitchen 310, hall at 310, hall by 322A, 322A, 322B, 322D, Suite 318, Finance hall, hall by stairwell, Finance by exit, Suite 303, Room	308C, 308D, rear hall 308, 306, 307, 301 kitchen, 301B, 301C, 301D, 301E, 301F, 302, 304, 305, 303A, 303D, 303C, 310A open, 310A, 310E, Hall at 310E, 310B, 310C, 311, Testing room, 311B, 311A, kitchen 310, hall at 310, hall by 322A, 322A, 322B, 322D, Suite 31B, Finance hall, hall by stairwell, Finance by exit, Suite 303, Room	308C, 308D, rear hall 308, 306, 307, 301 kitchen, 301B, 301C, 301D, 301E, 301F, 302, 304, 305, 303A, 303D, 303C, 310A open, 310A, 310E, Hall at 310E, 310B, 310C, 311, Testing room, 311B, 311A, kitchen 310, hall at 310, hall by 322A, 322A, 322B, 322D, Suite 31B, Finance hall, hall by stairwell, Finance by exit, Suite 303, Room	308C, 308D, rear hall 308, 306, 307, 301 kitchen, 301B, 301C, 301B, 301C, 301B, 301C, 301B, 302C, 304, 305, 303A, 303D, 303C, 310A open, 310A, 310E, Hall at 310E, 310B, 310C, 311, Testing room, 311B, 311A, kitchen 310, hall at 310, hall by 322A, 322A, 322A, 322A, 322A, 322B, 322D, Suite 318, Finance hall, hall by stairwell, Finance by exit, Suite 303, Room

Туре	Amount	Friability
T-TSI	SF-Square feet	F-Friable
S-Surfacing	LF-Linear feet	NF-Non-friable

M - Miscellaneous

Assessment Categories for Friable Materials

- 1. Damaged or significantly damaged TSI
- 2. Damaged (D) surfacing
- 3: Significantly damaged (SD) surfacing
- 4: Damaged or significantly damaged misc.
- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)

Date of Reinspection: 10/18/2023

School: Administration Building -3rd floor & common areas

Inspector Name: Lynne Brimhall

Address: Tufts Building 167 Holland Street, Somerville, MA

Inspector Signature:

License #: AI 061691

Material	Location (Homogeneous Area)	QTY	Friable	Phys Assess Category	Assumed ACM	Sample Date ACM Y or N	Recommendation	Amount/Location of Damage; Type of Damage	Schedule Begin/Complete	Special Cleaning
Small	322B, 332B main		F	5	Υ		Sample to prove			N
fissured	area, 322C,	SF					negative until such			
ceiling tile	office hall, large						time as it is proven			
(mixed in	room by 322E,						negative include in			
with other	large room by						O&M Plan			
tiles usually)	325A, waiting									
	area, 324, 318E,									
	318I, 318L,									
	318M, back hall									
	by 318,318 hall									
	by furnace, Suite									
	316, 316D, 315,									
	315A, 306, 307,									
	301B, 301E,									
	301F, 304, 310A									
	open area, 310A,									
	Copier B10,									
	310E, 311, Hall									
	right off elevator									
	(entire hall),									
	ceilings of hall									
	near stairs, Suite									
	308, 309, finance									
	reception, 303									
	entrance,									
	finance main									
i	area, Suite 303									

Туре	Amount	Friability
T-TSI	SF-Square feet	F-Friable
S-Surfacing	LF-Linear feet	NF-Non-friable
M - Miscellane	ous	

2. Damaged (D) surfacing

3: Significantly damaged (SD) surfacing

1. Damaged or significantly damaged TSI

4: Damaged or significantly damaged misc.

- **Assessment Categories for Friable Materials** 5: Suspect or proven ABCM with the potential for D (*one moderate)
 - 6: Suspect or proven ABCM with the potential for SD (*one high)
 - 7. Any remaining suspect or proven ACBM (*all low)

School: Administration Building -3rd floor & common areas

Address: Tufts Building 167 Holland Street, Somerville, MA

Date of Reinspection: 10/18/2023

Inspector Name: Lynne Brimhall

License #: AI 061691

Material	Location (Homogeneous Area)	QTY	Friable	Phys Assess Category	Assumed ACM	Sample Date ACM Y or N	Recommendation	Amount/Location of Damage; Type of Damage	Schedule Begin/Complete	Special Cleaning
Thin fissured ceiling tile	Finance hall, Finance reception, Suite 308, 309, Suite 303, 322H, Hall by finance, 301B, 301E, 301F, copier 310	509 SF	F	5	Y		Sample to prove negative until such time as it is proven negative include in O&M Plan			N
Large and small dots	303, 303D	62 SF	F	5	Y		Sample to prove negative until such time as it is proven negative include in O&M Plan			N
2x2 Rough ceiling tile	Rm 310	3024 SF	F	5	Y		Sample to prove negative until such time as it is proven negative include in O&M Plan			N

Туре	Amount	Friability
T-TSI	SF-Square feet	F-Friable
S-Surfacing	LF-Linear feet	NF-Non-friable

M - Miscellaneous

Assessment Categories for Friable Materials

- 1. Damaged or significantly damaged TSI
- 2. Damaged (D) surfacing
- 3: Significantly damaged (SD) surfacing
- 4: Damaged or significantly damaged misc.
- 5: Suspect or proven ABCM with the potential for D (*one moderate)
- 6: Suspect or proven ABCM with the potential for SD (*one high)
- 7. Any remaining suspect or proven ACBM (*all low)